

CORRECTIVE MEASURES REPORT

Chesterfield Power Station – Upper Ash Pond Chesterfield County, Virginia

Prepared for:
Dominion Energy Virginia
120 Tredegar Street
Richmond, Virginia 23219

Prepared by:
Schnabel Engineering
9800 Jeb Stuart Parkway, Suite 100
Glen Allen, Virginia 23059

Schnabel Reference No. 24560022.020

February 2025

TABLE OF CONTENTS

CERTIFICATION 1

1.0 INTRODUCTION..... 2

2.0 IMPLEMENTATION OF CORRECTIVE MEASURES..... 2

APPENDICES

Appendix A: Annual Inspection Report for Existing CCR Surface Impoundment (WSP, January 2024)

CERTIFICATION

This Corrective Measures Report for the Chesterfield Power Station's Upper Ash Pond was prepared by Schnabel Engineering. The document and Certification/Statement of Professional Opinion are based on and limited to information that Schnabel has relied on from Dominion Energy and others, but not independently verified.

On the basis of and subject to the foregoing, it is my professional opinion as a Professional Engineer licensed in the Commonwealth of Virginia that this document has been prepared in accordance with good and accepted engineering practices as exercised by other engineers practicing in the same discipline(s), under similar circumstances, at the same time, and in the same locale. It is my professional opinion that the document was prepared consistent with the requirements in the United States Environmental Protection Agency's "Standards for the Disposal of Coal Combustion Residuals in Landfills and Surface Impoundments" (CCR Rule, 40 CFR §257 Subpart D).

The use of the word "certification" and/or "certify" in this document shall be interpreted and construed as a Statement of Professional Opinion and is not and shall not be interpreted or construed as a guarantee, warranty, or legal opinion.

Andrew T. North, P.E.

Associate / Operations Leader

Name


Title



Signature

February 14, 2025

Date



1.0 INTRODUCTION

Chesterfield Power Station (Station) is owned and operated by Virginia Electric and Power Company d/b/a Dominion Energy Virginia (Dominion Energy). The Station is located in Chesterfield County, Virginia at 500 Coxendale Road, east of Interstate 95 (Richmond-Petersburg Turnpike) and south of the James River. The Upper Ash Pond (UAP), located at the Station, is regulated as an existing, inactive Coal Combustion Residuals (CCR) surface impoundment, as defined by the United States Environmental Protection Agency’s “Standards for the Disposal of Coal Combustion Residuals in Landfills and Surface Impoundments” (CCR Rule, 40 CFR §257 Subpart D). The UAP is also regulated as a dam by the Virginia Department of Conservation and Recreation (DCR), with Inventory Number 041045 (DCR Dam Permit).

In accordance with the requirements of §257.83(b) of the CCR Rule, an annual inspection was completed by others in 2023, which identified deficiencies associated with the CCR unit and recommendations for corrective measures. As required by §257.83(b)(5) of the CCR Rule, if a deficiency is identified during an inspection, the owner or operator of the unit must remedy the deficiency and prepare documentation detailing the corrective measures taken.

This Corrective Measures Report (Report) for the UAP was prepared by Schnabel Engineering, LLC (Schnabel) on behalf of Dominion Energy to detail the corrective measures taken to address the deficiencies identified in the Annual Inspection Report for Existing CCR Surface Impoundment dated January 5, 2024 (2023 Annual Inspection Report), which is included as Appendix A.

2.0 IMPLEMENTATION OF CORRECTIVE MEASURES

As identified in the 2023 Annual Inspection Report, the evaluation of a camera inspection of Outfall 005, the 24-inch discharge pipe from the UAP Stormwater Management Facility, indicated observations of concrete pipe joint seal degradation, water infiltration at the degraded pipe joint, and solids accumulation/deposition between the inlet riser structure and the discharge outlet. Additional evaluation of the conditions observed and repair of the joint as needed to seal the pipe and eliminate the infiltration were recommended.

Dominion Energy retained Insituform to install a cured-in-place pipe, i.e. to slip line, the entire length of Outfall 005 to remedy the deficiency. On December 18, 2024, the pipe was repaired and a camera inspection was completed. Andrew North, PE of Schnabel reviewed the camera inspection of the completed corrective measures. Implementation of the corrective measures was verified to have been completed to remedy the deficiencies.

APPENDIX A

ANNUAL INSPECTION REPORT FOR EXISTING CCR SURFACE IMPOUNDMENT (WSP, JANUARY 2024)



Date of Inspection: 11/6/2023
Facility: Chesterfield Upper Pond

Annual Inspection Report for Existing CCR Surface Impoundment
Reference: 40 CFR Section 257.83, *Inspection Requirements for CCR Surface Impoundments*

Owner Information


Name of Dam: Chesterfield Power Station Dam
Owner's Name: Virginia Electric and Power Company d.b.a. Dominion Energy
State ID #: DCR Inventory # 041045, VPDES # VA0004146
Owner Contact: Kevin Bishoff - Construction Project Manager
Dam Location: Chester, VA

Engineer Information

Name and Virginia License Number: Donald Mayer 029879
Firm Name: WSP USA Inc.
Firm Address: 1100 Boulders Parkway, Suite 503, Richmond, VA 23225
Telephone No.: 804-358-7900

Certification Statement

I certify that the inspection of the above listed CCR surface impoundment was conducted in conformance with the requirements listed in 40 CFR 257.83, and with generally accepted good engineering practices.



Engineer seal, signature and date

As used herein, the word certify shall mean an expression of the Engineer's professional opinion to the best of his or her information, knowledge and belief, and does not constitute a warranty or guarantee by the Engineer



Date of Inspection:
 Facility:

Was a review performed of available information regarding the status of the CCR unit, including files in the operating record?

Yes	No
X	

Was a visual inspection performed (i) to identify signs of stress or malfunction of the CCR unit and appurtenant structures, and (ii) of all hydraulic structures underlying the base or passing through the dike of the CCR unit for structural integrity and safe and reliable operation?

X	
---	--

Identify any changes in the geometry of the impounding structure since the previous annual inspection.

In accordance with the CCR Rule and the UAP Closure Plan prepared in accordance with 40CFR 257.102, the UAP is being prepared for removal of CCR material. Construction activities are supported by sump/pumping systems and cut areas will be temporarily covered with Wind Defender as the removal layer is completed. A camera inspection of the 72" discharge pipe from the UAP Stormwater Management Facility was conducted on August 9, 2023. PE evaluation of the video of the inspection indicated observations of concrete pipe joint seal degradation and solids accumulation/deposition at approximately 163 feet from the outlet location (approximately 35 feet from the inlet riser structure). The video showed that water was infiltrating at the pipe joint at this location. Additional evaluation of this condition is recommended, with repair of the joint as needed to seal the pipe and eliminate the infiltration.

Verify the type, location, and condition of existing instrumentation (e.g. flow meter or staff gauge). Document the maximum recorded readings of each instrument since the previous annual inspection.

Instrumentation		Location	Max. Reading	
Inclinometers	UAP-IN-01	SW Embankment	0.13	inches
	UAP-IN-02	SW Embankment	-0.15	inches
	UAP-IN-03	Southern Embankment	-0.12	inches
	UAP-IN-04	SE Embankment	0.06	inches
	UAP-IN-05	NE Embankment	0.03	inches
	UAP-IN-06	NW Embankment	0.03	inches
	TW-IN-01	NW Embankment Toe	-	inches
	TW-IN-02	NW Embankment Toe	-	inches
Piezometers	UAP-PZ-01	SW Embankment	2.60	feet
	UAP-PZ-02	SW Embankment	1.70	feet
	UAP-PZ-03	Southern Embankment	3.80	feet
	UAP-PZ-04	SE Embankment	7.47	feet
	UAP-PZ-05	NE Embankment	7.83	feet
	UAP-PZ-06	NW Embankment	4.55	feet
	TW-PZ-01	NW Embankment Toe	-	feet
	TW-PZ-02	NW Embankment Toe	-	feet

Notes:

- UAP Instrumentation was installed in 2021 to support pond closure activities.
- All instrumentation was observed to be in good condition.
- The maximum reading of the inclinometers was recorded as the maximum displacement of the tilt sensor in any direction (+ or -) relative to the baseline measurement when the instrument was installed.
- The maximum reading of the piezometers was recorded as the hydraulic head above mean sea level (MSL).
- TW-IN-01 and TW-PZ-01 were removed March 18, 2022. TW-IN-02 and TW-PZ-02 were removed July 12, 2022.

*READINGS PROVIDED BY OTHERS



Date of Inspection:
 Facility:

List the minimum, maximum, and present depth and elevation of impounded water and CCR since the previous annual inspection.

Water level in pond*:

Minimum Depth (ft)	<input type="text" value="0.0"/>	Maximum Depth (ft)	<input type="text" value="5 +/-"/>	Present Depth (ft)	<input type="text" value="3.5"/>
Minimum Elev. (Ft)	<input type="text" value="25.0"/>	Maximum Elev. (ft)	<input type="text" value="30.0"/>	Present Elev. (ft)	<input type="text" value="28.5"/>

*STORMWATER MANAGEMENT FACILITY

CCR level in Pond:

Minimum Depth (ft)	<input type="text" value="50.0"/>	Maximum Depth (ft)	<input type="text" value="115.0"/>	Present Depth (ft)	<input type="text" value="Varies*"/>
Minimum Elev. (Ft)	<input type="text" value="40.0"/>	Maximum Elev. (ft)	<input type="text" value="105.0"/>	Present Elev. (ft)	<input type="text" value="Varies*"/>

*CCR SURFACE TOPOGRAPHY VARIES BETWEEN MIN AND MAX ELEVATION ACROSS THE HORIZONTAL PROFILE OF THE SURFACE IMPOUNDMENT

Maximum Storage Capacity: Ac - Ft.

Present volume of the impounded water: Ac - Ft.

Present volume of the impounded CCR: Ac - Ft.

Present volume, total: Ac - Ft.

Identify any appearances of an actual or potential structural weakness of the CCR unit or existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures.

As described above, the water infiltration/leaking joint in the UAP Stormwater Management Facility discharge pipe should be further evaluated to determine potential operational or safety impacts and repaired as needed.

Identify any changes that may have affected the stability or operation of the impounding structure since the previous annual inspection.

At the time of the inspection, the UAP was being prepared for removal of CCR material. Construction activities are supported by sump/pumping systems and cut areas will be temporarily covered with Wind Defender as removal layers are completed. As described above, the water infiltration/leaking joint in the UAP Stormwater Management Facility discharge pipe should be further evaluated to determine potential stability or operational impacts and repaired as needed.

Additional comments

The Chesterfield Upper Ash Pond meets the definition of an existing surface impoundment under 40CFR 257.53 of the "Standards for the Disposal of Coal Combustion Residuals (CCR) in Landfills and Surface Impoundments". The Upper Ash Pond no longer receives CCRs and is being prepared for CCR removal. Construction activities are supported by sump/pumping systems and cut areas will be temporarily covered with Wind Defender as they are completed.