



Date of Inspection: 12/6/2022
 Facility: Class III Landfill

Annual Inspection Report for CCR Landfills

Reference: 40 CFR Section 257.84, *Inspection Requirements for CCR Landfills*

Owner Information

Name of Landfill: Cope Generating Plant Class III Ash Landfill
 Owner's Name: Dominion Energy South Carolina d.b.a. Dominion Energy
 State ID #: #LF3-00038
 Owner Contact: Robert Carroll, Operations Supervisor
 Landfill Location: Cope, SC

Engineer Information


Name and South Carolina License Number: Nakia W. Addison, PE 31497
 Firm Name: TRC Environmental Corp.
 Firm Address: 50 International Drive, Suite 150, Greenville, SC 29615
 Telephone No.: 864-275-1285

Certification Statement

I certify that the inspection of the above listed CCR landfill was conducted in conformance with the requirements listed in 40 CFR 257.84, and with generally accepted good engineering practices.



Engineer seal, signature and date



Firm Certificate of Authorization

As used herein, the word certify shall mean an expression of the Engineer's professional opinion to the best of his or her information, knowledge and belief, and does not constitute a warranty or guarantee by the Engineer



Date of Inspection: 12/6/2022
Facility: Class III Landfill

Was a review performed of available information regarding the status of the CCR unit, including files in the operating record?

Yes	No
X	

Was a visual inspection performed to identify signs of stress or malfunction of the CCR unit?

X	
---	--

Identify any changes in the geometry of the structure since the previous annual inspection

The top surface of the active area of the landfill is graded to slope to the northeast. To minimize erosion and reduce the area exposed to precipitation, vegetative cover is placed over all side slopes except for the north side slope. Temporary cover is actively being placed on the north side slope with hydro-seeding sceduled for Spring 2023.

Approximate volume of the CCR contained in the unit at the time of inspection

763,519 cubic yards.

Identify any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit

None observed.

Identify any other change(s) which may have affected the stability or operation of the CCR unit since the previous annual inspection.

No other changes observed since previous annual inspection.

Additional comments

None.