



Date of Inspection: 12/23/2020
Facility: Class III Landfill

Annual Inspection Report for CCR Landfills

Reference: 40 CFR Section 257.84, *Inspection Requirements for CCR Landfills*

Owner Information


Name of Landfill: Wateree Steam Operations Class III Ash Landfill
Owner's Name: Dominion Energy South Carolina d.b.a. Dominion Energy
State ID #: #LF3-00026
Owner Contact: Tatiana Rosser, Environmental Manager
Landfill Location: Eastover, SC

Engineer Information

Name and South Carolina License Number: Clark M. Archer, PE 23104
Firm Name: Dominion Energy Environmental Services
Firm Address: 220 Operations Way, MC C221, Cayce, SC 29033-3712
Telephone No.: 803-217-7185

Certification Statement

I certify that the inspection of the above listed CCR landfill was conducted in conformance with the requirements listed in 40 CFR 257.84, and with generally accepted good engineering practices.



Engineer seal, signature and date

As used herein, the word certify shall mean an expression of the Engineer's professional opinion to the best of his or her information, knowledge and belief, and does not constitute a warranty or guarantee by the Engineer



Date of Inspection: 12/23/2020
Facility: Class III Landfill

Was a review performed of available information regarding the status of the CCR unit, including files in the operating record?

Yes	No
X	

Was a visual inspection performed to identify signs of stress or malfunction of the CCR unit?

X	
---	--

Identify any changes in the geometry of the structure since the previous annual inspection

Fill continues in the active area of the landfill. The Ash Pond closure project was completed in 2020 and no further pond material was placed in the landfill. The top surface was graded to slope northwesterly and vegetative cover was placed over the entire top surface except for the active lift area located at the eastern end. The active lift area slopes southwesterly such that stormwater runoff sheet-flows to the southwest side. Vegetative cover is currently placed over all side slopes to minimize erosion and reduce the area exposed to precipitation.

Approximate volume of the CCR contained in the unit at the time of inspection

2,810,000 cubic yards.

Identify any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit

None observed.

Identify any other change(s) which may have affected the stability or operation of the CCR unit since the previous annual inspection.

Slope drains were installed along the southwest and southeast slopes to collect top surface stormwater runoff.

Additional comments

None.