

Date of Inspection: 5/25/2023

Facility: Bremo West Pond

# **Annual Inspection Report for Existing CCR Surface Impoundment**

Reference: 40 CFR Section 257.83, Inspection Requirements for CCR Surface Impoundments

### **Owner Information**

Name of Dam: Bremo Power Station West Pond Dam

Owner's Name: Virginia Electric and Power Company d.b.a. Dominion Energy Virginia

State ID #: DCR Inventory #065011

Owner Contact: W. Alan Leatherwood (434) 390-3256

Dam Location: Bremo Bluff, Virginia

# **Engineer Information**

Name and Virginia License Number: Donald Mayer 029879

Firm Name: WSP USA Inc. (fka Golder Associates)

Firm Address: 2108 W. Laburnum Ave, Suite 200, Richmond, VA 23227

Telephone No.: 804-358-7900

#### **Certification Statement**

I certify that the inspection of the above listed CCR surface impoundment was conducted in conformance with the requirements listed in 40 CFR 257.83, and with generally accepted good engineering practices.



Engineer seal, signature and date

As used herein, the word certify shall mean an expression of the Engineer's professional opinion to the best of his or her information, knowledge and belief, and does not constitute a warranty or guarantee by the Engineer



Date of Inspection: 5/25/2023
Facility: Bremo West Pond

	Yes	No
Was a review performed of available information regarding the status	Х	
of the CCR unit, including files in the operating record?		
Was a visual inspection performed (i) to identify signs of stress or	Х	
malfunction of the CCR unit and appurtenant structures, and (ii) of all	Λ	
hydraulic structures underlying the base or passing through the dike of		
the CCR unit for structural integrity and safe and reliable operation?		
Identify any changes in the geometry of the impounding structure since the p	revious	
annual inspection.		
None observed.		
Verify the type, location, and condition of existing instrumentation (e.g. flow	meter or st	aff
gauge). Document the maximum recorded readings of each instrument since		
annual inspection.		
A digital staff gauge was made operational in January 2021 and is monitored	remotely.	
Water levels are taken automatically on an hourly basis. Highest water level of	of 222.7 red	orded on
5/17/2023.		
		000
List the minimum, maximum, and present depth and elevation of impounded	water and	CCR
since the previous annual inspection.		
Water level in pond:		
	nt Depth (ft)	varies*
	ent Elev. (ft)	222.6
*NOTE: BOTTOM SURFACE TOPOGRAPHY VARIES IN ELEVATION ACROSS PO		
CCR level in Pond:		
Minimum Depth (ft) - Maximum Depth (ft) - Preser	nt Depth (ft)	-
Minimum Elev. (Ft) N/A* Maximum Elev. (ft) N/A* Prese	ent Elev. (ft)	N/A*
*NOTE: CCR REMOVED FROM POND AND OVEREXCAVATION COMPLETE AS	OF JANUA	RY 2020
Maximum Storage Capacity: 342 Ac - Ft.		
Procent volume of the impounded water:		
· ———		
· ———		
Present volume of the impounded water:  Present volume of the impounded CCR:  Present volume, total  234.0 Ac - Ft.  - Ac - Ft.  234.0 Ac - Ft.		



Date of Inspection: 5/25/2023

Facility: Bremo West Pond

Identify any appearances of an actual or potential structural weakness of the CCR unit or existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures.

None	observed	١.

Identify any changes that may have affected the stability or operation of the impounding structure since the previous annual inspection.

None observed.

#### Additional comments

The West Pond no longer receives CCRs. All CCR has been removed, 6-inch over excavation of soil has been completed and verified by Virginia DEQ in April 2020. Federal CCR Rule assessment groundwater monitoring continues to show that concentrations remain below groundwater protection standards. As a result, Dominion Energy intends to close the unit under Federal CCR Rule coverage in accordance with 40 CFR §257.102(c). At the time of my visit the West Pond was functioning as an influent storage pond for station source waters.