

This maple tree right here is a really good example of something we trimmed six to eight months ago. Our crew came in here with a bucket truck and trimmed the growth that could grow and affect our lines to where we would not be able to provide reliable electricity to our customers.