

Date of Inspection: 9/27/2019

Facility: CPS FFCP Facility

## **Annual Inspection Report for CCR Landfills**

Reference: 40 CFR Section 257.84, Inspection Requirements for CCR Landfills

## **Owner Information**

Name of Landfill: Chesterfield Power Station FFCP Management Facility

Owner's Name: Virginia Electric and Power Company d.b.a. Dominion Energy

State ID #: Solid Waste Permit #609

Owner Contact: Jannina Gahagan - Environmental Compliance Manager

Landfill Location: Chester, VA

## **Engineer Information**

Name and Virginia License Number: Daniel McGrath 040703

Firm Name: Golder Associates Inc.

Firm Address: 2108 W. Laburnum Ave, Suite 200, Richmond, VA 23227

Telephone No.: 804-358-7900

## **Certification Statement**

I certify that the inspection of the above listed CCR landfill was conducted in conformance with the requirements listed in 40 CFR 257.84, and with generally accepted good engineering practices.



Engineer seal, signature and date

As used herein, the word certify shall mean an expression of the Engineer's professional opinion to the best of his or her information, knowledge and belief, and does not constitute a warranty or guarantee by the Engineer



Date of Inspection: 9/27/2019
Facility: CPS FFCP Facility

	Yes	No
Was a review performed of available information regarding the status	Х	
of the CCR unit, including files in the operating record?		
Was a visual inspection performed to identify signs of stress or	Х	
Was a visual inspection performed to identify signs of stress or malfunction of the CCR unit?	Λ.	
Thursdiction of the centume.		
Identify any changes in the geometry of the structure since the previous annual	inspection	
None		
Approximate volume of the CCR contained in the unit at the time of inspection		
117,200 cubic yards		
Identify any appearances of an actual or potential structural weakness of the CC	R unit,	
in addition to any existing conditions that are disrupting or have the potential to	disrupt	
the operation and safety of the CCR unit		
None observed.		
Identify any other change(s) which may have affected the stability or operation	of the CCD i	ınit
since the previous annual inspection.	of the CCK u	11111
· · ·		
None observed.		
Additional comments		
None.		