☐ Chesterfield Landfill	☐ Clover Landfill	☐ Mt Storm Phase A/Phase B Landfills		
☑ VCHEC Landfill	☐ Yorktown Landfill			
		_		
September 25, 2015	Inspected By:	Michael J. Winters		
Michael J. Winters	Virginia PE Registration Number	033623		
	☑ VCHEC Landfill  September 25, 2015	■ VCHEC Landfill     ■ Yorktown Landfill     September 25, 2015     ■ Inspected By:     Wichael I. Winters     ■ Virginia PE Registration		

## **Professional Engineer Certification Statement**

I certify that the inspection of the above listed CCR Landfill was conducted in conformance with the requirements listed in 40 CFR Section 257.84, *Inspection Requirements for CCR Landfills*, and with generally accepted good engineering practices.

Print Name:	Michael J. Winters	Title:	Engineer III
Signature:	Hele Gertenten	Date:	1/13/16

Place Stamp Here

Michael John Winters

No. 033623



## Inspection Results - VCHEC Landfill

Was a review performed of available information regarding the status and condition of the CCR unit, including files in the operating record?		Yes	No
		X	
		Yes	No
Was a visual inspection performed to identify signs of stress or malfunction of the CCR unit?			
Identify any changes in the geometry of the unit since the previous	annual inspection.	=	
Continued placement of CCR in accordance with the Station's approx	red plans and specifica	ations.	
Present volume of the CCR contained in the unit at the time of the inspection (cubic yards)	3,914,800		
Identify any appearances of an actual or potential structural weakness conditions that are disrupting or have the potential to disrupt the			
None observed.			
Identify any changes that may have affected the stability or operati	on of the unit since t	he previ	ious
annual inspection.			
None observed.			
Additional comments			
None.			